

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5

77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

Aug 22 9 og AH '97

AUG 1 1 1997.

REPLY TO THE ATTENTION OF:

(AE-17J)

CERTIFIED MAIL RETURN RECEIPT REQUESTED

Johnny W. Reising, Project Manager Fernald Remedial Action United States Department of Energy Ohio Field Office, Fernald Area Office P.O. Box 53705 Cincinnati, Ohio 45253-88705

RE: Application for Approval to Use Environmental Measurement to Demonstrate Compliance with the National Emission Standards for Hazardous Air Pollutants, Subpart H

Dear Mr. Reising:

The United States Environmental Protection Agency (USEPA) has reviewed the information submitted in the Request for Approval dated May 23, 1997, by the United States Department of Energy (USDOE) Fernald Environmental Management Project (FEMP) for applicability of continuous monitoring requirements.

Based upon the requirements stated in 40 CFR 61.93(b) (5) being fully met, and the information submitted in the Request for Approval, and previous submittals of the Integrated Environmental Management Plan for the FEMP, the USEPA grants the USDOE FEMP approval to use the environmental measurements, as requested for compliance with National Emission Standards for Hazardous Air Pollutants for radionuclides (NESHAPs), Subpart H. This approval is granted based upon the above referenced submittals and a site compliance review conducted July 21 through 25, 1997.

Changes to this approval will be evaluated as conditions change ant the site and may be modified as USEPA deems necessary to assure compliance with the NESHAPs regulations.

If you have any additional questions or need further clarification on this determination, feel free to contact Michael Murphy, of my staff, at (312) 353-6686.

Sincerely yours,

Michaeld Murphy for Jack Barnett, Chief

Jack Barnett, Chief
Radiation and Indoor Air Section



cc: Donald Schregardus Ohio EPA

> Tom Tucker Ohio EPA

Ruth Vandegrift Ohio Department of Health

Graham Mitchell OEPA, Dayton Office